



**Forum: Graveurs CD/DVD**

**Topic: Echec de gravure DVD+R**

**Subject: Echec de gravure DVD+R**

Posté par: Anonyme

Posté le : 16/3/2008 15:30:04

Bonjour, étant novice j'ai besoin de votre aide à tous. J'ai un problème de gravure, je peux graver les CD, DVD RW, mais pas les DVD+R. J'ai essayé avec plusieurs logiciels, différentes marques de DVD, mais après 8 ou 10% echec de gravure. La dernière a été faite avec Alcohol 120% et voilà le registre d'erreur. ##### System Information

##### Windows XP Professional 5.1 Service Pack 2 (Build 2600)

Processor info: Intel(R) Core(TM)2 CPU 6300 @ 1.86GHz x 2 (1866MHz) Memory Available to Windows: 1 047 852 KB ##### Program Information

##### File Name: C:Program FilesAlcohol SoftAlcohol 120alcohol\_.exe

Company Name: Alcohol Soft Development Team Description: Alcohol 120% Original: Alcohol.exe

Product: Alcohol 120% Trademarks: Alcohol Soft Development Team Copyright: Copyright(C)

2002-2006 Alcohol Soft Development Team Version: 1.9.6 ( Build 4719 ) Date: 2006/11/20 Size:

1666944 Bytes Hash: e924b6a93abd8b4a1b0b0a709a16dd8e Hash(1):

d1a71e26c6484f6e3c73f78e7f2a9d4e64a3b47b09eff52c92aaae6e7926c1f Hash(2):

754c9687fdb69cb9f833c79770700c53e7fff6f92fcc02f33be965965952cd80 Loader:

c:windowsexplorer.exe File Name: C:Program FilesAlcohol SoftAlcohol 120alcoholx.dll Company

Name: Alcohol Soft Co., Ltd. Description: Alcohol virtual device control library Original: alcoholx.dll

Product: Alcohol Copyright: Copyright (C) 2000-2006 Version: 4.8.0 ( Build 0 ) Date: 2006/11/18

Size: 792472 Bytes Hash: 83eeec45bf18fbd60c56a2e3a0191057 File Name: C:Program

FilesAlcohol SoftAlcohol 120devsupp.dll Company Name: Alcohol Soft Development Team

Description: Alcohol Software Device Capability Library Original: devsupp.dll Product: Alcohol

Software Device Capability Library Copyright: Copyright(C) 2002-2006 Alcohol Soft Development

Team Version: 2.5.1 ( Build 2317 ) Date: 2006/11/17 Size: 58752 Bytes Hash:

a0f7ad7f40c6f36e240f295bcc99de20 ##### User Information

##### Licensed to: coooool it down! Registered User ID: 2007

##### Options Setting ##### Devices control

interface: Default Driver Control Interface CPU Priority Level: High Memory Buffer Size (MB): 128

Examine the accuracy of data read from physical device: Yes Enable Enhanced Weak Sector

Scanner during dumping: No Overburn disc(s): No Turn off "Auto-Select best write speed" function if

possible: No Fill memory buffer before recording discs: Yes Book Type DVD+R/DVD+RW disc as

DVD-ROM while burning: No Ignore Media Type: No RMPS (Recordable Media Physical Signature)

Emulation: No BAD Sectors Emulation: No Sub-Channel Data Fixed & Emulation: No Laserlock

Emulation: No Current Language: French ##### Device(s) List

##### (E:) HL-DT-ST DVDRAM GSA-H12N (jraid, Port 4, Bus 0, Target

0, Lun 0) (F:) LITE-ON DVD SHD-16P1S (jraid, Port 4, Bus 0, Target 1, Lun 0) (K:) SE0040D

RKY288K (a5377z9i, Port 5, Bus 0, Target 0, Lun 0) ##### Installed Device

Drivers List ##### 000.fcl 1394BUS.SYS a5377z9i.SYS ACPI.sys afd.sys

arp1394.sys atapi.sys audstub.sys Beep.SYS BOOTVID.dll Cdfs.SYS cdrom.sys CLASSPNP.SYS

disk.sys dmio.sys dmload.sys drmk.sys dump\_atapi.sys dump\_WMILIB.SYS Dxapi.sys dxg.sys

dxgthk.sys Fips.SYS fltMgr.sys Fs\_Rec.SYS ftdisk.sys hal.dll HDAudBus.sys HIDCLASS.SYS

HIDPARSE.SYS hidusb.sys HTTP.sys imapi.sys intelppm.sys ipnat.sys ipsec.sys isapnp.sys

JGOGO.sys jraid.sys kbdclass.sys kbdhid.sys KDCOM.DLL kmixer.sys ks.sys KSecDD.sys

mnmdd.SYS mouclass.sys mouhid.sys MountMgr.sys mrxdav.sys mrxsmb.sys Msfs.SYS msgpc.sys  
mssmbios.sys Mup.sys NDIS.sys ndistapi.sys ndisuiio.sys ndiswan.sys NDProxy.SYS netbios.sys  
netbt.sys nic1394.sys Npfs.SYS ntdll.dll Ntfs.sys Null.SYS nv4\_disp.dll nv4\_mini.sys ohci1394.sys  
parport.sys PartMgr.sys ParVdm.SYS pci.sys pciide.sys PCIINDEX.SYS pfc.sys portcls.sys  
psched.sys ptlink.sys rasacd.sys rasl2tp.sys rasppoe.sys rasptp.sys raspti.sys rdbss.sys  
RDPCDD.sys rdpr.sys redbook.sys Rtenicxp.sys RtkHDAud.sys SCSIIPORT.SYS secdrv.sys  
serenum.sys serial.sys snapman.sys sptd.sys sr.sys srv.sys swenum.sys sysaudio.sys tcpip.sys  
TDI.SYS tdrpman.sys termdd.sys tifsilt.sys timntr.sys TUKERNEL.EXE update.sys usbccgp.sys  
USBDD.SYS usbehci.sys usbhub.sys USBPORT.SYS usbscan.sys USBSTOR.SYS usbhci.sys  
vga.sys VIDEOPRT.SYS VolSnap.sys wanarp.sys watchdog.sys wdmaud.sys win32k.sys  
WMILIB.SYS ##### Detailed Information of Device(s) #####  
//////////////////////////////////// (E:) HL-DT-ST DVDROM GSA-H12N(4:0) detail  
information. ////////////////////////////////// Vendor Identification: HL-DT-ST Product  
Identification: DVDROM GSA-H12N Production Revision Level: UL02 Location: jraid, Port 4, Bus 0,  
Target 0, Lun 0 Support recording method: DAO, RAW SAO, RAW SAO+SUB, RAW DAO(96), DVD  
DAO BURN-Free Technology: Unknown Auto-Select best write speed: Not Supported \*\*\* NOT listed  
in Alcohol&#39;s database. Please report to development team -\* Note: This information below is  
provided by the unit, it might be inaccurate. \*- -\* This software does not use this information! \*-  
Removable media: Yes Version: ATAPI (INF-8090i/INF-8020i/INF-8028i) Response Data Format:  
02h CD-R Read/Write: Yes/Yes CD-RW Read/Write: Yes/Yes Read CD-R Fixed Packet: Yes Test  
Write: Yes DVD-ROM Read: Yes DVD-R Read/Write: Yes/Yes DVD-RAM Read/Write: Yes/Yes  
Audio Play: Yes Composite Audio and Video Data Stream: No Digital output (IEC958) on port 1  
Supported: No Digital output (IEC958) on port 2 Supported: No Mode 1 Form 2: Yes Mode 2 Form 2:  
Yes Multi-Session: Yes BUF: Yes CD-DA Commands supported: Yes CD-DA Stream is Accurate:  
Yes R-W Supported: No R-W De-interleaved and Corrected: No C2 Pointers Support: Yes ISRC  
Supported: Yes UPC Supported: Yes Read Bar Code: No Lock media into the drive: Yes Currently  
drive Lock state: Unlocked Prevent Jumper: No Eject Command: Yes Separate volume levels: Yes  
Separate channel mute: Yes Changer Supports Disc Present: No Software slot selection: No Side  
change capable: No P through W in Lead-In: Yes ////////////////////////////////// (F:)  
LITE-ON DVD SHD-16P1S(4:1) detail information. //////////////////////////////////  
Vendor Identification: LITE-ON Product Identification: DVD SHD-16P1S Production Revision Level:  
GS07 Location: jraid, Port 4, Bus 0, Target 1, Lun 0 -\* Note: This information below is provided by  
the unit, it might be inaccurate. \*- -\* This software does not use this information! \*- Removable  
media: Yes Version: ATAPI (INF-8090i/INF-8020i/INF-8028i) Response Data Format: 02h CD-R  
Read/Write: Yes/No CD-RW Read/Write: Yes/No Read CD-R Fixed Packet: Yes Test Write: No  
DVD-ROM Read: Yes DVD-R Read/Write: Yes/No DVD-RAM Read/Write: No/No Audio Play: Yes  
Composite Audio and Video Data Stream: Yes Digital output (IEC958) on port 1 Supported: No  
Digital output (IEC958) on port 2 Supported: No Mode 1 Form 2: Yes Mode 2 Form 2: Yes  
Multi-Session: Yes BUF: No CD-DA Commands supported: Yes CD-DA Stream is Accurate: Yes  
R-W Supported: No R-W De-interleaved and Corrected: No C2 Pointers Support: Yes ISRC  
Supported: Yes UPC Supported: Yes Read Bar Code: No Lock media into the drive: Yes Currently  
drive Lock state: Unlocked Prevent Jumper: No Eject Command: Yes Separate volume levels: Yes  
Separate channel mute: Yes Changer Supports Disc Present: No Software slot selection: No Side  
change capable: No P through W in Lead-In: Yes  
#####  
##### Source Disc/Image Information ##### Type:  
Fichier image ISO Standard Chemin: D:TELE  
AZUREUSWindows.XP.Sweet.4.5.FRENCH.DVDxp-sweet45 Nom: xp-sweet45.iso Taille: 2926.11  
MB Session : 1 Piste : 1 Session 01: Piste 01: DVD, Nombre de secteurs: 1498170(2.86 GB),

Adresse: 000000

#####

##### Dumping/Recording Progress Log #####

\*\*\*\*\* Time stamp of this log file: 16/03/2008 10:55:41 \*\*\*\*\* 10:55:41 Infos processeur : Intel(R) Core(TM)2 CPU 6300 @ 1.86GHz x 2 (1866MHz) 10:55:41 Mémoire disponible pour Windows :1 047 852 KB 10:55:41 Taille de la mémoire tampon : 128 MB 10:55:41 Lecture du fichier image: D:TELE AZUREUSWindows.XP.Sweet.4.5.FRENCH.DVDxp-sweet45xp-sweet45.iso 10:55:41 DVD Source Info : Session: 1, Piste: 1, Nombre de secteurs: 2.86 GB / 332:55:45 10:55:43 (E:) HL-DT-ST DVDRAM GSA-H12N(4:0): Méthode d'écriture / Vitesse 10:55:43 Gravure - DVD DAO - 18.0X (24930 Ko/Sec) (E:) HL-DT-ST DVDRAM GSA-H12N(4:0) - Media format: DVD+R 10:56:57 (E:) HL-DT-ST DVDRAM GSA-H12N(4:0) - [Write ERROR] LBA: 232288, Length: 16 S:KEY - 04/09/01 - "Tracking Servo Failure" 10:56:57 (E:) HL-DT-ST DVDRAM GSA-H12N(4:0): Gravure échouée ! 10:56:57 Message d'erreur [04/09/01] - Tracking Servo Failure 10:56:57 (E:) HL-DT-ST DVDRAM GSA-H12N(4:0): Gravure échouée ! 10:56:57 Lecture du fichier image annulée ! 10:56:59 Une erreur est survenue durant la procédure de gravure! Veuillez consulter le registre et rapporter les erreurs au support technique.

#####

Si une personne peut résoudre mon problème je lui en serais reconnaissant . Merci d'avance  
Carole**Configuration:** Windows XPMessage édité par Ankyo pour ajouter la balise Code.